Inspection Report

Visionary Holdings

Property Address:
1920 SW 2nd Terrace
Cape Coral FL 33991



MEF Home Inspections LLC

Matthew Foster HI13455
99 Vivante Blvd. Unit 99210
Punta Gorda, FL 33950
941-740-9635

Matthew Foster



TABLE OF CONTENTS

Cover Page 1

Table of Contents 3

Intro Page 4

1 Roof 5

2 Garage 7

3 Attic 8

4 Exterior 10

5 Wall Exteriors 11

6 Structure 13

7 Interior 14

8 Bathrooms 16

9 Laundry Room 18

10 Electrical 19

11 Plumbing 21

12 Heating 22

13 Cooling 23

14 Pool and Spa 24

General Summary 26

Invoice 29

Date: 11/3/2026	**Time:** 10:00 AM	**Report ID:** 20261103-1920-SW-2nd-Terrace
Property: 1920 SW 2nd Terrace Cape Coral FL 33991	**Customer:** Visionary Holdings	**Real Estate Professional:** Katie Martin

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Standards of Practice: InterNACHI International Association of Certified Home Inspectors	**Type of building::** Single Family (1 story)	**Approximate Square Footage::** 2000
Approximate Year of Original Construction:: 2023	**Occupancy::** Unoccupied, empty of furniture	**Weather during the Inspection::** Clear
Significant precipitation in last 3 days:: Yes	**Temperature during inspection::** Over 65 (F) = 18 (C)	**Ground/Soil surface condition:** Dry

RESULTS AT A GLANCE

103	9	22
ITEMS INSPECTED Total number in report.	SUMMARY COMMENTS Total number in report.	PHOTOS Total number in report.

1. ROOF

DESCRIPTION

The roof inspection portion of the General Home Inspection will not be as comprehensive as an inspection performed by a qualified roofing contractor. Because of variations in installation requirements of the huge number of different roof-covering materials installed over the years, the General Home Inspection does not include confirmation of proper installation. Home Inspectors are trained to identify common deficiencies and to recognize conditions that require evaluation by a specialist. Inspection of the roof typically includes visual evaluation of the roof structure, roof-covering materials, flashing, and roof penetrations like chimneys, mounting hardware for roof-mounted equipment, attic ventilation devices, ducts for evaporative coolers, and combustion and plumbing vents. The roof inspection does not include leak-testing and will not certify or warranty the roof against future leakage. Other limitations may apply and will be included in the comments as necessary.

ITEMS: ROOF

1.0 ROOF STRUCTURE EXTERIOR

INSPECTED

1.1 UNDERLAYMENT

INSPECTED

1.2 ROOF FLASHING

INSPECTED

1.3 PLUMBING, COMBUSTION VENTS, SKYLIGHTS

INSPECTED

1.4 ROOF DRAINAGE SYSTEM

INSPECTED, REPAIR/REPLACE

One or more downspouts discharged roof drainage next to the foundation. This condition can effect the ability of the soil to support the weight of the structure above and can cause damage related to soil/foundation movement. The Inspector recommends the installation of downspout extensions to discharge roof drainage a minimum of 6 feet from the foundation.



1.4 Item 1 (Picture)



1.4 Item 2 (Picture)

1.5 ASPHALT SHINGLES

INSPECTED

2. GARAGE

DESCRIPTION

Inspection of the garage typically includes examination of the following:general structure; floor, wall and ceiling surfaces; operation of all accessible conventional doors and door hardware; vehicle door condition and operation proper electrical condition including Ground Fault Circuit Interrupter (GFCI) protection; interior and exterior lighting; stairs and stairways proper firewall separation from living space; and proper floor drainage

ITEMS: GARAGE

2.0 VEHICLE DOORS

INSPECTED

2.1 CONVENTIONAL DOORS

INSPECTED

2.2 FLOORS

INSPECTED

2.3 WALLS

INSPECTED

2.4 CEILING

INSPECTED

2.5 FIRE SEPARATION

INSPECTED

2.6 GARAGE GENERAL CONDITION

INSPECTED

3. ATTIC

DESCRIPTION

Inspection of the attic typically includes visual examination the following:roof structure (framing and sheathing); roof structure ventilation; thermal envelope; electrical components (wiring, junction boxes, outlets, switches and lighting); plumbing components (supply and vent pipes, bathroom vent terminations) and HVAC components (drip pans, ducts, condensate and TPR discharge pipes)

ITEMS: ATTIC

3.0 ATTIC ACCESS

INSPECTED, NOT INSPECTED

No access to attic above garage, due to boat being parked under opening. Inspector was able to inspect partial attic through master bedroom closet access.



3.0 Item 1 (Picture)

3.1 TRUSS ROOF FRAMING

INSPECTED

3.2 ROOF SHEATHING

INSPECTED

3.3 ROOF STRUCTURE VENTILATION

INSPECTED

3.4 ATTIC ELECTRICAL

INSPECTED

3.5 ATTIC PLUMBING

INSPECTED

3.6 MISC ATTIC CONDITIONS (LEAKAGE, DEBRIS, ETC.)

INSPECTED

3.7 ATTIC THERMAL ENVELOPE

INSPECTED

3.8 ATTIC HVAC

INSPECTED

4. EXTERIOR

DESCRIPTION

Inspection of the home exterior typically includes: exterior wall covering materials; exterior trim; window and door exteriors; adequate surface drainage; driveway and walkways; window wells; exterior electrical and plumbing components; and retaining wall conditions that may affect the home structure. The potential for dangers/damage associated with trees- such as falling branches or root damage to foundations- varies with tree species and age, and requires an arborist evaluation.
The General Home Inspection does not include inspection of landscape irrigation systems, fencing or swimming pools/spas unless pre-arranged as ancillary inspections.

ITEMS: EXTERIOR

4.0 EXTERIOR VIEWS

INSPECTED

4.1 DRIVEWAY

INSPECTED

4.2 WALKWAYS

INSPECTED

4.3 GENERAL GROUNDS

INSPECTED

4.4 TREES

INSPECTED

4.5 PORCH

INSPECTED

5. WALL EXTERIORS

ITEMS: WALL EXTERIORS

5.0 DOOR EXTERIORS

INSPECTED


5.1 WINDOW EXTERIORS

INSPECTED

5.2 EXTERIOR WALL PENETRATIONS

INSPECTED, COSMETIC

Exterior wall penetrations had gaps that should to be sealed with an appropriate sealant to prevent moisture and insect entry. All work should be performed by a qualified contractor.



5.2 Item 1 (Picture)
Lefft side under service panel

5.3 EXTERIOR TRIM

INSPECTED

5.4 STUCCO

INSPECTED, REPAIR/REPLACE

(1) On the left side of dwelling there is a hole in the stucco that needs patched.




5.4 Item 1 (Picture)

(2) Minor cracking was visible in stucco covering exterior walls of the home. Cracks exceeding 1/16-inch in width should be filled with an appropriate material to prevent future damage from moisture and monitored in the future for continued activity.



5.4 Item 2 (Picture)
Left side



5.4 Item 3 (Picture)
Left side



5.4 Item 4 (Picture)
Right side



5.4 Item 5 (Picture)
Right side



5.4 Item 6 (Picture)
Right side




5.4 Item 7 (Picture)
Right side

(3) Minor stucco damage on right side of dwelling.



5.4 Item 8 (Picture)



5.4 Item 9 (Picture)

6. STRUCTURE

DESCRIPTION

The General Home Inspection includes inspection of the home structural elements that were readily visible at the time of the inspection. This may include the: foundation; walls; floor structure; and/or roof structure. Soils vary in their stability and ability to support the weight of a structure. Minor cracking is normal with some common foundation materials, is typically limited to the material surface, is not a structural concern, and may not be commented on. Cracking related to soil/foundation movement indicates the potential for present or future structural concerns and will be commented on to the best of the inspector's ability.
Much of the home structure is hidden behind exterior and interior roof, floor, wall, and ceiling coverings, or is buried underground. Because the General Home Inspection is limited to visual and non-invasive methods, this report may not identify all structural deficiencies. Identification of portions of the wall structure not directly visible requires logical assumptions on the part of the Inspector that are based on the Inspectors past experience and knowledge of common building practices.

Upon observing indications that structural problems may exist that are not readily visible, or the evaluation of which lies beyond the Inspector's expertise, the inspector may recommend evaluation or testing by a specialist that may include invasive measures, which would require homeowner permission.

ITEMS: STRUCTURE

6.0 CONCRETE MASONRY UNIT EXTERIOR WALLS

INSPECTED

6.1 FLOOR STRUCTURE

INSPECTED

6.2 SLAB-ON-GRADE

INSPECTED

7. INTERIOR

ITEMS: INTERIOR

7.0 FLOORS

INSPECTED

7.1 WALLS

INSPECTED

7.2 CEILINGS

INSPECTED

7.3 LIGHTING

INSPECTED

7.4 ENVIRONMENTAL HAZARDS

INSPECTED

7.5 MISC. COMPONENTS: CEILING FANS, DOORBELLS, DETECTORS, ETC.

INSPECTED, REPAIR/REPLACE

The doorbell was inoperable. The Inspector recommends correction by a qualified electrical contractor.



7.5 Item 1 (Picture)

7.6 DOORS

INSPECTED

7.7 WINDOWS AND SKYLIGHTS

INSPECTED, REPAIR/REPLACE

A window in the master bathroom shot up when window was unlocked. This is typically caused by faulty window balance springs, or a spiral balance was wound to tight.



7.7 Item 1 (Picture)

7.8 INTERIOR TRIM

INSPECTED

7.9 CABINETS, COUNTERTOPS, AND SINKS

INSPECTED

7.10 KITCHEN APPLIANCES

INSPECTED, REPAIR/REPLACE

Garbage disposal inoperable at time of inspection.



7.10 Item 1 (Picture)



7.10 Item 2 (Picture)

8. BATHROOMS

DESCRIPTION

Inspection of the bathrooms typically includes the following:walls, floors and ceiling; sink (basin, faucet, overflow); cabinets (exteriors, doors, drawers, undersink); toilet/bidet tub and shower (valves, showerhead, walls, enclosure); electrical (outlets, lighting); and room ventilation

ITEMS: BATHROOMS

8.0 LIGHTING

INSPECTED

8.1 VENTILATION

INSPECTED

8.2 CABINETS

INSPECTED

8.3 CABINET UNDERSINK CONDITION

INSPECTED

8.4 SINK(S)

INSPECTED


8.5 TOILET

INSPECTED


8.6 SHOWER

INSPECTED, REPAIR/REPLACE

Grout maintenance needed at 1st shared bathroom shower.



8.6 Item 1 (Picture)



8.6 Item 2 (Picture)

8.7 BATHTUB

INSPECTED

8.8 MEDICINE CABINET

INSPECTED

8.9 MIRRORS

INSPECTED

9. LAUNDRY ROOM

DESCRIPTION

In addition to those items typically inspected as part of the interior, inspection of the laundry room includes examination of the following:dryer connections and venting; room ventilation; and provision of proper clothes washer waste pipe.

ITEMS: LAUNDRY ROOM

9.0 RECEPTACLES, SWITCHES, CONNECTIONS

INSPECTED

9.1 WASHER/DRYER

INSPECTED

9.2 DRYER VENTING

INSPECTED

10. ELECTRICAL

DESCRIPTION

Over the years, many different types and brands of electrical components have been installed in homes. Electrical components and standards have changed and continue to change. Homes electrical systems are not required to be updated to meet newly enacted electrical codes or standards. Full and accurate inspection of electrical systems requires contractor-level experience. For this reason, full inspection of home electrical systems lies beyond the scope of the General Home Inspection.
The General Home Inspection is limited to identifying common electrical requirements and deficiencies. Conditions indicating the need for a more comprehensive inspection will be referred to a qualified electrical contractor.Inspection of the home electrical system typically includes visual inspection of the following:service drop: conductors, weatherhead, and service mast; electric meter exterior; service panel and sub-panels; service and equipment grounding; system and component bonding; and visible branch wiring: receptacles (representative number), switches, lighting

ITEMS: ELECTRICAL

10.0 GENERAL ELECTRICAL SYSTEM DESCRIPTION

INSPECTED

10.1 GENERAL ELECTRICAL SYSTEM CONDITION

INSPECTED

10.2 ELECTRIC METER

INSPECTED

10.3 SERVICE ENTRANCE CONDUCTORS

INSPECTED

10.4 SERVICE PANEL CABINET AND COVER

INSPECTED

10.5 SERVICE PANEL WIRING

INSPECTED

10.6 SERVICE DISCONNECT

INSPECTED

10.7 OVERCURRENT PROTECTION DEVICES

INSPECTED

10.8 SERVICE GROUNDING & BONDING

INSPECTED

10.9 EQUIPMENT GROUNDING & BONDING

INSPECTED

10.10 SUB-PANEL CABINET & BONDING

INSPECTED

10.11 SUB-PANEL COVERS

INSPECTED

10.12 SUB PANEL WIRING

INSPECTED

10.13 ELECTRICAL RECEPTACLES (INTERIOR)

INSPECTED

10.14 ELECTRICAL RECEPTACLES (EXTERIOR)

INSPECTED

10.15 GFCI/AFCI ELECTRICAL RECEPTACLES

INSPECTED

10.16 VISIBLE BRANCH WIRING

INSPECTED

10.17 SWITCHES

INSPECTED

10.18 BRANCH CIRCUITS

INSPECTED

11. PLUMBING

DESCRIPTION

Inspection of the plumbing system typically includes (limited) operation and visual inspection of: water supply source (identification as public or private); sewage disposal system (identification as public or private); water supply/ distribution pipes; drain, waste and vent (DWV) system; water heater (type, condition and operation); gas system; and sump pump (confirmation of installation/operation).

ITEMS: PLUMBING

11.0 EXTERIOR PLUMBING

INSPECTED

11.1 WATER SUPPLY AND DISTRIBUTION

INSPECTED

11.2 SEWAGE AND DWV SYSTEMS

INSPECTED

11.3 ELECTRIC WATER HEATER

INSPECTED

12. HEATING

DESCRIPTION

Heating system inspection will not be as comprehensive as that performed by a qualified heating, ventilating, and air-conditioning (HVAC) system contractor. For example: identification of cracked heat exchangers requires a contractor evaluation. Report comments are limited to identification of common requirements and deficiencies. Observed indications that further evaluation is needed will result in referral to a qualified HVAC contractor. The general home inspection does not include any type of heating system warranty or guaranty. Inspection of heating systems is limited to basic evaluation based on visual examination and operation using normal controls. Report comments are limited to identification of common requirements and deficiencies. Observed indications that further evaluation is needed will be referred to a qualified heating, ventilating, and air-conditioning (HVAC) contractor. Inspection of heating systems typically includes (limited) operation and visual inspection of: the heating appliance (confirmation of adequate response to the call for heat); proper heating appliance location; proper or adequate heating system configuration; exterior cabinet condition; fuel supply configuration and condition; combustion exhaust venting; heat distribution components; proper condensation discharge; and temperature/pressure relief valve and discharge pipe (presence, condition, and configuration).

ITEMS: HEATING

12.0 AIR HANDLER

INSPECTED

12.1 THERMOSTAT

INSPECTED

13. COOLING

DESCRIPTION

Inspection of home cooling systems typically includes visual examination of readily observable components for adequate condition, and system testing for proper operation using normal controls. Cooling system inspection will not be as comprehensive as that performed by a qualified heating, ventilating, and air-conditioning (HVAC) system contractor. Report comments are limited to identification of common requirements and deficiencies. Observed indications that further evaluation is needed will result in referral to a qualified HVAC contractor. To avoid the potential for system damage, the air-conditioning system will not be operated if the outside air temperature is below 65 degrees F (17 C).

ITEMS: COOLING

13.0 CONDENSER UNIT

INSPECTED

13.1 EVAPORATOR COILS

INSPECTED

13.2 AC SYSTEM PERFORMANCE

INSPECTED

14. POOL AND SPA

DESCRIPTION

Inspection of swimming pools and spas typically includes visual examination of readily-observable components/ systems and operation of mechanical and electrical equipment using normal controls.

ITEMS: POOL AND SPA

14.0 BARRIER SYSTEM

INSPECTED

14.1 VESSEL

INSPECTED

14.2 DECK

INSPECTED, COSMETIC

Hole in paver pool decking near skimmer should be filled.



14.2 Item 1 (Picture)

14.3 LIGHTS

INSPECTED

14.4 MISC. COMPONENTS (DRAINS, LADDER, SKIMMER, VENTURI)

INSPECTED

14.5 FILL

INSPECTED

14.6 ELECTRICAL SYSTEM

INSPECTED

14.7 CONTROL SYSTEMS

INSPECTED

14.8 FILTERS

INSPECTED

14.9 HEATING SYSTEM

INSPECTED

14.10 PLUMBING SYSTEM

INSPECTED, REPAIR/REPLACE

Minor leaks visible for the plumbing at pool equipment.



14.10 Item 1 (Picture)



14.10 Item 2 (Picture)

14.11 PUMP

INSPECTED

14.12 WATER QUALITY

INSPECTED

GENERAL SUMMARY

MEF Home Inspections LLC
99 Vivante Blvd. Unit 99210
Punta Gorda, FL 33950
941-740-9635

Customer
Visionary Holdings

Address
1920 SW 2nd Terrace
Cape Coral FL 33991

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling;** or **warrants further investigation by a specialist,** or **requires subsequent observation.** This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

1. ROOF

1.4 ROOF DRAINAGE SYSTEM

INSPECTED, REPAIR/REPLACE

One or more downspouts discharged roof drainage next to the foundation. This condition can effect the ability of the soil to support the weight of the structure above and can cause damage related to soil/foundation movement. The Inspector recommends the installation of downspout extensions to discharge roof drainage a minimum of 6 feet from the foundation.

5. WALL EXTERIORS

5.4 STUCCO

INSPECTED, REPAIR/REPLACE

(1) On the left side of dwelling there is a hole in the stucco that needs patched.

(2) Minor cracking was visible in stucco covering exterior walls of the home. Cracks exceeding 1/16-inch in width should be filled with an appropriate material to prevent future damage from moisture and monitored in the future for continued activity.

(3) Minor stucco damage on right side of dwelling.

7. INTERIOR

7.5 MISC. COMPONENTS: CEILING FANS, DOORBELLS, DETECTORS, ETC.

INSPECTED, REPAIR/REPLACE

The doorbell was inoperable. The Inspector recommends correction by a qualified electrical contractor.

7.7 WINDOWS AND SKYLIGHTS

INSPECTED, REPAIR/REPLACE

A window in the master bathroom shot up when window was unlocked. This is typically caused by faulty window balance springs, or a spiral balance was wound to tight.

7.10 KITCHEN APPLIANCES

INSPECTED, REPAIR/REPLACE

Garbage disposal inoperable at time of inspection.

8. BATHROOMS

8.6 SHOWER

INSPECTED, REPAIR/REPLACE

Grout maintenance needed at 1st shared bathroom shower.

14. POOL AND SPA

14.10 PLUMBING SYSTEM

INSPECTED, REPAIR/REPLACE

Minor leaks visible for the plumbing at pool equipment.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is

provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge http://www.HomeGauge.com : Licensed To Matthew Foster

INVOICE

MEF Home Inspections LLC
99 Vivante Blvd. Unit 99210
Punta Gorda, FL 33950
941-740-9635
Inspected By: Matthew Foster

Inspection Date: 11/3/2026
Report ID: 20261103-1920-SW-2nd-Terrace

Customer Info:	**Inspection Property:**
Visionary Holdings **Customer's Real Estate Professional:** Katie Martin	1920 SW 2nd Terrace Cape Coral FL 33991

Inspection Fee:

Service	Price	Amount	Sub-Total
Pre-Inspection	150.00	1	150.00

Tax $0.00
Total Price $150.00

Payment Method:
Payment Status:
Note: